# **HOME REPORT**

AVERUEROAD Estate Agents

FLAT 1 CHURCH HALL NEWTON PORT HADDINGTON EH41 3LX



# ENERGY PERFORMANCE CERTIFICATE





# **Energy Performance Certificate (EPC)**

# Scotland

#### Dwellings

#### FLAT 1 CHURCH HALL, NEWTON PORT, HADDINGTON, EH41 3LX


Dwelling type: Date of assessment: Date of certificate: Total floor area: Primary Energy Indicator: Ground-floor flat 09 September 2024 10 September 2024 152 m<sup>2</sup> 100 kWh/m<sup>2</sup>/year Reference number: Type of assessment: Approved Organisation: Main heating and fuel: 8402-8617-3022-5606-1143 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas


#### You can use this document to:

#### · Compare current ratings of properties to see which are more energy efficient and environmentally friendly

#### Estimated energy costs for your home for 3 years\*

<sup>t</sup> based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions





## **Energy Efficiency Rating**

£3,297

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band B (83)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

## Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$  emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band B (83)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282. THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

# FLAT 1 CHURCH HALL, NEWTON PORT, HADDINGTON, EH41 3LX 10 September 2024 RRN: 8402-8617-3022-5606-1143

## Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, as built, insulated (assumed)	****	****
Roof	(another dwelling above)	—	
Floor	Solid, insulated (assumed)	—	_
Windows	Fully double glazed	★★★☆	<b>★★★★</b> ☆
Main heating	Boiler and radiators, mains gas	****	<b>★★★★</b> ☆
Main heating controls	Programmer, room thermostat and TRVs	<b>★★★</b> ☆	<b>★★★★</b> ☆
Secondary heating	None	—	
Hot water	From main system	★★★☆	<b>★★★★</b> ☆
Lighting	Low energy lighting in all fixed outlets	****	*****

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 18 kg  $CO_2/m^2/yr$ .

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.7 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

# FLAT 1 CHURCH HALL, NEWTON PORT, HADDINGTON, EH41 3LX 10 September 2024 RRN: 8402-8617-3022-5606-1143

Estimated energy costs for this home			
	Current energy costs	Potential energy costs	Potential future savings
Heating	£2,256 over 3 years	£2,256 over 3 years	
Hot water	£555 over 3 years	£555 over 3 years	Net en elle ble
Lighting	£486 over 3 years	£486 over 3 years	Not applicable
Totals	£3,297	£3,297	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

**Recommendations for improvement** 

None

### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

### Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	7,324	N/A	N/A	N/A
Water heating (kWh per year)	2,232			

#### About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number: Company name/trading name: Address:	Mr. Jonathan Hunter EES/014665 D M Hall Chartered Surveyors LLP 17 Corstorphine Road Edinburgh EH12 6DD
Phone number:	0131 4776006
Email address:	jonathan.hunter@dmhall.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

# SINGLE SURVEY





## survey report on:

Property address	FLAT, 1 CHURCH HALL, NEWTON PORT, HADDINGTON, EH41 3LX
------------------	--

Customer	Mr Alistair Ross

Customer address	Flat 1 Church Hall, Newton Port, Haddington, EH41 3LX
------------------	--

Prepared by	DM Hall LLP

Date of inspection	9th September 2024
--------------------	--------------------



## PART 1 - GENERAL

## 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

<sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.



The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

## 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.<sup>2</sup>

## 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

<sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

they assign the same to any other party in writing.

## 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

## 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

### 1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

## **PART 2 - DESCRIPTION OF THE REPORT**

## 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

## 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

## 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

## Terms and Conditions

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

ground floor flat positioned within a two storey building containing three units.	Description	
---	-------------	--

Accommodation	ALL ON GROUND FLOOR:- Entrance Hall, Lounge/Dining
	Room/Kitchen, Master Bedroom with En- Suite Shower Room,
	Bedroom Two and Family Bathroom.

Gross internal floor area (m²)	152 square metres or thereby.
Neighbourhood and location	The property forms part of an established private residential estate

	made up with a variety of house types located within the Town of Haddintgton. Adequate amenities are available closeby.

Age Built circa 1850 and subsequently converted.
--

Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
Weather	Bright and dry preceded by a mixed spell of weather.

	No chimney stacks although the bell tower is still in situ.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.
	Multiple pitched roof overlaid with slates. Ridges have been formed in metal cappings as have the valley gutters. There are coping stones at roof edges presumably with cement fillet flashings.

Rainwater fittings	Visually inspected with the aid of binoculars where appropriate. Predominantly plastic half round gutters discharge into round downpipes. Sections of cast iron appear to exist.
Main walls	Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or

inspected. The property is of traditional solid stone construction, pointed externally.

Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible.
	Doors and windows were not forced open. Double glazed PVC windows throughout.
	The flat entrance door is formed in timber.

External decorations	Visually inspected.
	Painted timberwork and cast iron rainwater fittings where appropriate.

Conservatories / porches	None.

Communal areas	Circulation areas visually inspected.
	Communal garden grounds to the rear of the building laid to block paving bounded by pointed stonework walling.
	Communal stair with secure entrance system.

Garages and permanent outbuildings	None.
Outside areas and boundaries	Visually inspected. Communal garden grounds to rear with allocated parking space to
Ceilings	front of the building over mono block surface. Visually inspected from floor level.
	Ceilings are presumably formed in plaster.

Floors including sub floors

Cellars

Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Internal walls are presumably formed in plasterboard.

Flooring appears to be of floating floor construction.

Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Internal doors are formed in etched timber. Profile timber facings and skirtings noted.
	The kitchen comprises of wall and base units overlaid with laminated worktops.

Chimney breasts and fireplaces	None.
--------------------------------	-------

Internal decorations	Visually inspected.
	Painted and tiled finishes noted.
	Internal doors, skirtings and facings have a painted/stained finish.

None.

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. Mains supply. The meter and consumer unit are located within the hall cupboard. PVC cabling connects to 13 amp power outlets.

Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains supply.

Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Mains supply.
	Visible pipework is formed in a mixture of copper and PVC plumbing materials.
	Conventional white sanitaryware fitted throughout.


Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	There is a gas fired wall mounted boiler located within bedroom 2 wardrobe. This serves radiators and underfloor heating. It is assumed that the boiler also provides domestic hot water direct to the fittings.

Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	Drainage is connected to the main public sewer.

Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	Smoke detector installed.
	Legislation by the Scottish Government, which took effect from February 2022, requires all residential properties to have a system of inter-linked smoke alarms and heat detectors. Carbon monoxide detectors are also required where appropriate. Purchasers should appraise themselves of the requirements of this legislation, and engage with appropriately accredited contractors to ensure compliance.

Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

Any additional limits to inspection	At the time of my inspection, the property was occupied, fully furnished and all floors were covered. Personal effects noted throughout the property and within cupboards. As a result, my inspection was subsequently restricted.
	No access gained to any roof space or sub-floor areas.
	Not all roof slopes or elevations could be seen from ground level due to sight line/boundary restrictions.
	Not all windows were tested.
	Parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.
	I have not carried out an inspection for Japanese Knotweed and unless otherwise stated, for the purposes of the valuation I have assumed that there is no Japanese Knotweed or other invasive plants within the boundaries of the property or in neighbouring properties.
	The report does not include an asbestos inspection. However asbestos was widely used in the building industry until around 2000, when it became a banned substance. If the possibility of asbestos based products has been reported within the limitations of the inspection and you have concerns you should engage a qualified asbestos surveyor.
	Random testing for dampness was undertaken internally with the use of a moisture meter where accessible and considered appropriate.
	Concealed areas beneath and around bath/shower trays were not visible. Water spillage in these areas can often be discovered unexpectedly with resultant damage to concealed parts of the fabric.
	The inspection is not a fire or life safety risk assessment and should not be relied on as a risk assessment inspection. Further advice should be sought if a specific risk assessment of the property and building that it forms part of is required.
	Where repairs are required at height compliance with Health and Safety legislation often requires the use of scaffolding which can significantly impact on the cost of repair. Pricing repairs is out with the remit of this report but it would be prudent to consider costs and budgeting before offering. The various trades can advise further.



## 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	The property has been affected by previous movement but within the limitations of the inspection there was no evidence to suggest that this is ongoing.

Dampness, rot and infestation	
Repair category	1
Notes	No obvious evidence of significant dampness, rot or wood boring insect infestation.

Chimney stacks	
Repair category	-
Notes	None.

Roofing including roof space	
Repair category	2
Notes	Due to the complex nature of the roof structure, ongoing maintenance should be anticipated to the slated roof coverings.

Rainwater fittings	
Repair category	1
Notes	No significant defects evident.
	Cast iron rainwater fittings require more than typical maintenance.
	Rainwater goods should be tested during periods of heavy rainfall to ascertain

Rainwater fittings	
Repair category	1
Notes	their true condition.

Main walls	
Repair category	2
Notes	Spalled/weathered stonework most notably to front elevation. Some previous repaired cracks observed.

Windows, external doors and joinery	
Repair category	1
Notes	No significant defects evident.

External decorations	
Repair category	1
Notes	No significant defects evident. Ongoing decorative works should be anticipated to all external timbers and cast iron rainwater goods to prolong life span.

Conservatories/porches	
Repair category	-
Notes	None.

Communal areas	
Repair category	1
Notes	Ongoing maintenance should be anticipated to the stonework boundary walling.

Garages and permanent outbuildings	
Repair category	-
Notes	None.

Outside areas and boundaries	
Repair category	1
Notes	No significant defects evident.

Ceilings	
Repair category	1
Notes	No significant defects evident.

Internal walls	
Repair category	1
Notes	No significant defects evident.

Floors including sub-floors	
Repair category	1
Notes	No significant defects evident.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No significant defects evident.

Chimney breasts and fireplaces	
Repair category	-
Notes	None.

Internal decorations	
Repair category	1
Notes	No significant defects evident.

Cellars	
Repair category	-
Notes	None.

Electricity	
Repair category	1
Notes	It is recommended that all electrical installations be checked every five years or on change of ownership to keep up to date with frequent changes in Safety Regulations. Further advice will be available from a qualified NICEIC/SELECT registered Contractor. It should be appreciated that only recently constructed or rewired properties will have installations which fully comply with IET regulations.

Gas	
Repair category	1
Notes	Trade bodies governing gas installations currently advise that gas appliances should be tested prior to change in occupancy and thereafter at least once a year by a Gas Safe registered contractor. It is assumed that gas appliances comply with relevant regulations.

F         Water, plumbing and bathroom fittings	
Repair category	1
Notes	No significant defects evident. Ongoing maintenance should be anticipated to the sealant around the sanitary fittings. Failure to seals can result in dampness/decay within hidden areas of the property.

Heating and hot water	
Repair category	1
Notes	No significant defects evident.
	It is assumed that the heating and hot water systems have been properly serviced and maintained on a regular basis and installed in accordance with the relevant regulations.
	It is assumed that the central heating system has been properly installed and maintained to meet with all relevant regulations, particularly in respect of flue and ventilation requirements.
	Boilers and central heating systems should be tested and serviced by a Gas Safe registered contractor on an annual basis to ensure their safe and efficient operation.

Drainage	
Repair category	1
Notes	No significant defects evident.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	-
Roofing including roof space	2
Rainwater fittings	1
Main walls	2
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	1
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	-
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

#### **Category 3**

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

#### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

## 3. Accessibility information

#### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

#### Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

#### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

The property has been converted to form its current configuration. It is assumed all necessary Local Authority and other consents have been obtained for alterations and the appropriate documentation, including Building Warrants and Completion Certificates issued. If any works did not require consent then it is assumed they meet the standards required by the Building Regulations or are exempt.

The property may be listed and as such the cost of repair or reinstatement works are likely to be higher than normal. Any works considered necessary will require to be carried out in consultation with the Local Authority Planning Department and Historic Environment Scotland.

The subjects form part of a flatted development and it has been assumed that maintenance/repair costs of the common parts of the building will be shared on an equitable basis with adjoining proprietors. It is therefore assumed that the cost of common repairs detailed within the report will be apportioned accordingly although exact liability should be confirmed.

#### Estimated reinstatement cost for insurance purposes

£700,000 (SEVEN HUNDRED THOUSAND POUNDS).

It should be noted this sum is an estimate calculated by using a rate per square metre based on information provided by Building Cost Information Service (BCIS).

For Listed buildings and historic properties within Conservation Areas you should seek further specialist insurance advice.

#### Valuation and market comments

In my opinion, the market value of the property as inspected may be fairly stated at £350,000 (THREE HUNDRED AND FIFTY THOUSAND POUNDS).

Following buoyant market conditions over a prolonged period through the Covid 19 pandemic, there are now indications of a return to a more balanced level of supply and demand.

Report author	Jonathan Hunter

Company name	DM Hall LLP

Address       17 Corstorphine Road, Edinburgh, EH12 6DD	
---	--

 Date of report
 12th September 2024

# Mortgage Valuation Report



Property Address	
Address Seller's Name Date of Inspection	FLAT, 1 CHURCH HALL, NEWTON PORT, HADDINGTON, EH41 3LX Mr Alistair Ross 9th September 2024
Property Details	
Property Type	HouseBungalowChaletPurpose built maisonetteCoachStudioConverted maisonettePurpose built flatX Converted flatTenement flatFlat over non-residential useOther (specify in General Remarks)
Property Style	Detached       Semi detached       Mid terrace       End terrace         Back to back       High rise block       X Low rise block       Other (specify in General Remarks)
Does the surveyor be e.g. local authority, mi	lieve that the property was built for the public sector, Yes X No ilitary, police?
Flats/Maisonettes only	y Floor(s) on which located 0 No. of floors in block 2 Lift provided? Yes X No
Approximate Year of (	No. of units in block 3 Construction 1850
Tenure	
X Absolute Ownership	Leasehold Ground rent £ Unexpired years
Accommodation	
Number of Rooms	1       Living room(s)       2       Bedroom(s)       1       Kitchen(s)         2       Bathroom(s)       0       WC(s)       0       Other (Specify in General remarks)
	cluding garages and outbuildings) 152 m <sup>2</sup> (Internal) 190 m <sup>2</sup> (External)
Residential Element (	greater than 40%) X Yes No
Garage / Parking / G	Outbuildings
Single garage Available on site?	Double garage       X Parking space       No garage / garage space / parking space         X Yes       No
Permanent outbuilding	gs:
None.	

# Mortgage Valuation Report

Construction							
Walls	Brick	X Stone Cavity X Slate	Concrete Steel frame Asphalt	Timber frame	Other	(specify in Gen	eral Remarks)
	Lead		Artificial slate	Flat glass fibre	Other	(specify in Gen	eral Remarks)
Special Risks							
Has the property s	suffered struct	ural moveme	nt?			X Yes	No
If Yes, is this rece	nt or progress	ive?				Yes	XNo
Is there evidence, immediate vicinity		ason to anticip	pate subsidence, h	eave, landslip o	r flood in the	Yes	X No
If Yes to any of the	e above, provi	de details in	General Remarks.				
Service Connec	tion						
Based on visual ir of the supply in G			es appear to be no	on-mains, please	e comment or	n the type ar	nd location
Drainage	X Mains	Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None				
Brief description of Gas fired boiler							
Site							
	ues to be veri	fied by the co	onveyancer. Please	provide a brief	description in	General R	emarks
Rights of way     Agricultural land in	X Shared drive	es / access		enities on separate	site Share	ed service conn	
Location							
Residential suburb     Commuter village		idential within to note village		esidential / commerc d rural property		y commercial (specify in Ge	neral Remarks)
Planning Issues	5						
Has the property I If Yes provide det			/ altered? X Yes	s 🗌 No			
Roads							
X Made up road	Unmade road	Partly of	completed new road	Pedestrian ac	ccess only	Adopted	Unadopted

#### General Remarks

The general condition of the property appears consistent with its age and type of construction.

The property has been converted to form its current configuration. It is assumed all necessary Local Authority and other consents have been obtained for alterations and the appropriate documentation, including Building Warrants and Completion Certificates issued. If any works did not require consent then it is assumed they meet the standards required by the Building Regulations or are exempt.

The property may be a listed building and as such the cost of repair or reinstatement works are likely to be higher than normal. Any works considered necessary will require to be carried out in consultation with the Local Authority Planning Department and Historic Environment Scotland.

The subjects form part of a flatted development and it has been assumed that maintenance/repair costs of the common parts of the building will be shared on an equitable basis with adjoining proprietors. It is therefore assumed that the cost of common repairs detailed within the report will be apportioned accordingly although exact liability should be confirmed.

The property has been affected by previous movement but within the limitations of the inspection there was no evidence to suggest that this is ongoing.

#### **Essential Repairs**

None noted within the limitations of my inspection.

Estimated cost of essential repairs £ 0	Estimated	cost of	essential	repairs £	0
---	-----------	---------	-----------	-----------	---

Retention recommended? Yes

X No Amount £

0

# Mortgage Valuation Report

#### **Comment on Mortgageability**

The property forms suitable security for normal mortgage purposes subject to individual lenders guidelines.

Valuations	
Market value in present condition	£ 350,000
Market value on completion of essential repairs	£ -
Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 700,000
Is a reinspection necessary?	Yes X No
Buy To Let Cases	
What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis?	£
Is the property in an area where there is a steady demand for rented accommodation of this type?	Yes No
Declaration	


Signed	Security Print Code [552148 = 9022 ] Electronically signed by:-
Surveyor's name	Jonathan Hunter
Professional qualifications	MSc MRICS
Company name	DM Hall LLP
Address	17 Corstorphine Road, Edinburgh, EH12 6DD
Telephone	0131 624 6600
Fax	0131 624 6609
Report date	12th September 2024

# PROPERTY QUESTIONNAIRE





# property questionnaire



Note for sellers

П

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

## Information to be given to prospective buyer(s)

	How long have you	owned the property?	SINCE	16/8/22	
2.	Council tax	29Y)	ra wabana	ant of second view	141 A

L	A B C D F F G H			
3	Parking			
	What are the arrangements for parking at your property? (Please tick all that apply)			
Γ	• Garage			
	Allocated parking space		2	
	• Driveway	<u>←</u> 2020 J	- 72 N.T 19 D	
Γ	Shared parking		e e e de a	
	• On street	e e e	; : : :	
	• Resident permit			
	Metered parking			
	Other (please specify):	=/_C	late	
4.	Conservation area		18758 1.1.11	
	Is your property in a designated Conservation Area (that is Yes an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?			
F				
5.	Listed buildings			
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Yes No		
6.	Alterations/additions/extensions	isid.		
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes No	inspectani Nationali	
	<u>If you have answered yes</u> , please describe below the changes which you have made:			
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Yes	den artic	
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.			
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:			
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	Yes		
	If you have answered yes, please answer the three questions below:	No		
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes No		
	(ii) Did this work involve any changes to the window or door openings?	Yes No		

(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):

Please give any guarantees which you received for this work to your solicitor or estate agent.

$\Box$							
7.	Central heating						
a.	Is there a central heating system in your property?	Yes					
	(Note: a partial central heating system is one which does not heat all the main rooms of the property —	No Partia					
	the main living room, the bedroom(s), the hall and the bathroom).	2555 733 2135 <sup>1</sup> 13					
	<u>If you have answered yes or partial</u> – what kind of central heating is there?	in a company					
	(Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	N Jac					
	<u>If you have answered yes</u> , please answer the three questions below:	 auter					
	(i) When was your central heating system or partial central heating system installed? $\sim \sim \sim \sim$						
	(ii) Do you have a maintenance contract for the central heating system?	Yes					
	If you have answered yes, please give details of the company with which you have a maintenance contract:	i isria					
	(iii) When was your maintenance agreement last renewed? (Please pl the month and year).	rovide					
8.	Energy Performance Certificate	sav pi					
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes No					
9.	Issues that may have affected your property	897.0					
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?						
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	Yes No					
b.	Are you aware of the existence of asbestos in your property?						
	If you have answered yes, please give details:	01,306 1077 R					
		0500 G					
10	. Services	himit Said an an a					
a. I	Please tick which services are connected to your property and give do the supplier:	etails o					
Se	ervices Connected Supplier	/0 /					
Ga ga	s or liquid petroleum						

SISTI

MATCH

SLUTTIN

cas

H

Water mains or private

water supply

Electricity

Ма	ins drainage		Scottick	- Sea Stored				
Tel	ephone	×						
Ca	ble TV or satellite	$\checkmark$	SKY					
Bro	badband		EE					
L				1993년 18 - 1993년 - 1993년 1995 - 1993년 - 1993년 - 1993년 1997 - 1993년 - 199				
b.	Is there a septic tank system at your property? <u>If you have answered yes</u> , please answer the two questions below:							
	(iv) Do you have appro from your septic tank			ang an na Rinna a suile				
	(v) Do you have a mai tank?							

Yes No

Yes No

Yes No

Don't Know

If you have answered yes, please give details of the company with which you have a maintenance contract:

1.

		-
11.	Responsibilities for shared or common areas	i yes, picase g
а.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? If you have answered yes, please give details:	Don't Know
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? If you have answered yes, please give details: for wish	Yes No Not applicable r€C
c.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Yes Nø
d.	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries? NCA If you have answered yes, please give details:	Yes No
	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details: M\\n	Yes No
	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.) <u>If you have answered yes</u> , please give details:	Yes
12.	Charges associated with your property	
	Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	Yes

b.	Is there a common buildings insurance policy?				Yes Ngơ Don't Kr	now
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?					now
с.	Please give details of any other charges you for the upkeep of common areas or repair w residents' association, or maintenance or st	ISIS				
13.	Specialist works			en en les services	internet in Maria	
а.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?			Yes No	Production of the state of the	
	<u>If you have answered yes</u> , please say what were for, whether you carried out the repai or if they were done before you bought the	rs (a	and v	vhen)		303 170V 201812 1981
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?			Yes Nø	n partine a subsection and a subsection of the	
	<u>If you have answered yes</u> , please give deta	ils:		96 <u>0. 13 1</u> 5	141 S. 01.293	barrowens ender sold and
c.	<u>If you have answered yes</u> to 13(a) or (b), o guarantees relating to this work?	lo yo	ou ha	ave any	Yes No	nan sinan sinan sinan data . Anma Seffaar naa data . A
	If you have answered yes, these guarantee by the purchaser and should be given to yo soon as possible for checking. If you do not yourself <u>please write below who has these</u> your solicitor or estate agent will arrange fo obtained. You will also need to provide a de work carried out. This may be shown in the estimate.	Jaciba shi yumatisati				
	Guarantees are held by:	2010	ः ज	mai zistit	ni olfsmin Johns	se confirm that Une inf ave aur ionswirdg <mark>e en:</mark>
	T			********		
14.	Guarantees					
a.	Are there any guarantees or warranties for					
		No	Yes	Don't know	With title deeds	Lost
(i)	Electrical work					
(ii)	Roofing			~		
(iii)	Central heating			/		
(iv)	National House Building Council (NHBC)					
(v)	Damp course			$\checkmark$		
-		1	1	the second s	1	
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)			/	- ×	
	(for example, cavity wall insulation,	eds'	, plea rela	ase give te(s):	details of th	ie

•

	and the second sec	s - s - statulita
15.	Boundaries	
So far prope	So far as you are aware, has any boundary of your property been moved in the last 10 years?	Yes
	If you have answered yes, please give details:	Don't know

16.	Notices that affect your property	n na: Nna:
	In the past three years have you ever received a notice:	
a.	advising that the owner of a neighbouring property has made a planning application?	Yes
b.	that affects your property in some other way?	Yes
c.	that requires you to do any maintenance, repairs or improvements to your property?	Yes No
	If you have answered yes to any of $a-c$ above, please give the notices your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.	to ′

## Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Mr. R. Ror Anisnair Roor

9



ABERDEEN aberdeen\_residential@ dmhall.co.uk 01224 594172

AYR ayr@dmhall.co.uk 01292 286974

DUMFRIES dumfries@dmhall.co.uk 01387 254318

DUNDEE dundee@dmhall.co.uk 01382 873100

DUNFERMLINE dunfermline@dmhall.co.uk 01383 621262

EDINBURGH edinburghresidential@ dmhall.co.uk 0131 624 6600

ELGIN elgin@dmhall.co.uk 01343 548501

FALKIRK falkirk@dmhall.co.uk 01324 628321

GALASHIELS galashiels@dmhall.co.uk 01896 752009 GLASGOW (Residential) glasgowresidential@ dmhall.co.uk 0141 636 4141

HAMILTON hamilton@dmhall.co.uk 01698 284939

INVERNESS inverness@dmhall.co.uk 01463 241077

INVERURIE inverurie@dmhall.co.uk 01467 624393

IRVINE irvine@dmhall.co.uk 01294 311070

KIRKCALDY kirkcaldy@dmhall.co.uk 01592 598200

LIVINGSTON livingston@dmhall.co.uk 01506 490404 OBAN oban-admin@dmhall. co.uk 01631 564225

**PAISLEY** Enquiries are now dealt with at our Glasgow Hub.

PERTH perth@dmhall.co.uk 01738 562100

PETERHEAD peterhead@dmhall.co.uk 01779 470220

ST ANDREWS standrews@dmhall.co.uk 01334 844826

STIRLING stirling@dmhall.co.uk 01786 475785

